


UT=-0.020  
PT=-1.600

UT=-0.020  
PT=-1.900

±0,000

±0,000

**03**



3260

1750  
1950(450)

1690

440

6870

3605

440

2600

1750

3500

5570

1.090

3370

2685

1965

115

400

1850

115

400

1435

115

1695

0888

320

115

300

115

625

450

175

700

440

1300

875

1575

2970

600

600(2050)

2000

1.087

+0,000

00